

Inspection Report

Customer	Bossman	Product	RF Shielded Tent	
Date of Inspection	11/1/2024	Model	RFT-07	
Inspection Method	TESOP-RF-03 Serial Number		2411012	
Comments	All parts passed inspection and are accounted for.			

Visual Inspection				
ltem	Quantity	Repaired	Location / Description	Pass / Fail
Rips / Cuts	0	NA	NA	PASS
Fabric Discoloration	0	NA	NA	PASS
Frame Dents	0	NA	NA	PASS
Hemming Defects	0	NA	NA	PASS
Doorway Defects	0	NA	NA	PASS
Filter Damage	0	NA	NA	PASS
I/O Panel Damage	0	NA	NA	PASS
Power Panel Damage	0	NA	NA	PASS

	Shielding Effectiveness			
Frequency	Reference Level (dB)	Measured Level (dB)	Shielding Effectiveness (dB)	Pass / Fail
900 MHz	-5	-79	-74	PASS
2.4 GHz	-11	-89	-78	PASS
5.8 GHz	-37	-97	-60	PASS

	Parts Inventory			
Part	Description / Dimensions (mm)	Quantity		Pass / Fail
		Set	Actual	
Aluminum Pipe	ø28 x L950 x T1.5	12	12	PASS
Magnet Board (Door)	L100 x W50 x T3	23	23	PASS
Magnet Board (Door)	L310 x W50 x T3	1	1	PASS
Magnet Board (Inner)	L415 x W50 x T3	5	5	PASS
Corner Bracket	ø28	8	8	PASS
Bolts		24	24	PASS
Tent	W900 x L900 x H900	1	1	PASS
Frame Bag	W120 x L1000 x H120	1	1	PASS
Tent Bag	W200 x L900 x H450	1	1	PASS
Bracket bag	W160 x L160 x H160	1	1	PASS
I/O panel	SMA x 3 / N Type x 3	1	1	PASS
Power panel	120V/16A AC Filter x 1	1	1	PASS
User manual		1	1	PASS



Quality Inspector:

Caleb Crites Celeb B Gites

Quality Inspector Signature: